About the installation of　8871 under WIN 10　:

Please change the WINDOWS system setting by the following procedure: .

1. Please go to Settings → Update & Security →

# Recovery → Restart now .

2. Select "Toubleshoot "

## 3. Select   " Advanced options "

4. Select "Startup setting"

Please check if the system is under " Disable driver signature enforcement ", if this line is at ENABLE status , please click "Restart " to change the setting

5. After OS reboot , the system will go to "Startup settings " , please click ==F7 to disable== **the "driver signature enforcement "**

After this setting , windows will advice security as installing the driver and software of
8871 .Please select 〝 Install this drier software anyway〞